Dart Aerospace Ltd. Wednesday, 17/09/2008 10:32:52 AM Date: User: Jean-Luc Menard **Process Sheet** : HINGE ASSEMBLY LOWER DOOR : CU-DAR001 Dart Helicopters Services **Drawing Name** Customer Job Number : 42050 : 13562 **Estimate Number** : D3813041 P.O. Number **Part Number** D3813 PREE **Drawing Number** This Issue : 17/09/2008 S.O. No. : : N/A : NC **Project Number** Prsht Rev. : PREL : MACHINED PARTS First Issue : // Type **Drawing Revision** Material Previous Run 3 Um: **Due Date** : 24/09/2008 Qty: Each Written By Checked & Approved By New Issue 08-09-09 JLM Verified By:EC Comment : Est Rev:Á **Additional Product** Job Number: Description: Seq. #: **Machine Or Operation:** D38131 Hinge, Upper Door 1.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 3.0000_Each(s) Hinge, Upper Door Batch: 2.0 D35183 Comment: Qty.: 1.0000 Each(s)/Unit Total: 3.0000 Each(s) Stainless Steel Ball Joint Rod End Batch: 3.0 NAS5096 1.0000 Each(s)/Unit Total: 3.0000 Each(s) Comment: Qty.: Nut BATCH: 4.0 MS124738 Total: 3.0000 Each(s) Comment: Qty.: 1.0000 Each(s)/Unit Heli-Coil 3/8-24 unf BATCH: SMALL & MEDIUM FAB RESOURCE 1 SMALL FAB 5.0 Comment: SMALL & MEDIUM FAB RESOURCE 1 1-Install helicoils as per Dwg D3813 2-Install Ball joint and nut loosely as per Dwg D3813

Page 1

Date: Wednesday, 17/09/2008 10:32:52 AM User: Jean-Luc Menard **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: HINGE ASSEMBLY LOWER DOOR Job Number: 42050 Part Number: D3813041 Job Number: Seq. #: **Machine Or Operation:** Description: ENGINEERING STEP 6.0 QC5 APRROVAL Comment: INSPECT WORK TO CURRENT STEP 7.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock 08/10/03 Location: 8.0 FINAL INSPECTION/W/O RELEASE QC21 Comment: FINAL INSPECTION/W/O RELEASE Job Completion POSITIVE RECALL 00252A

THEORY THEORETHIA